

CRC MATERIAL SAFETY DATA SHEET

CRC Industries, Inc. • 885 Louis Drive • Warminster, PA 18974 • (215) 674-4300

FOR 24 HR. EMERGENCY INFORMATION CALL CHEMTREC 1-800-424-9300

PRODUCT NAME: BELT DRESSING AEROSOL

#-HSUS03065
PRODUCT- 3065

(Page 1 of 2)

1. INGREDIENTS	CAS #	ACGIH TLV	OSHA PEL	OTHER LIMITS	%
Polybutene	9003-29-6	NA	NA		20-30
Isohexanes	107-81-5	500 ppm	500 ppm		40-50
Propane	74-98-6	NA	1000 ppm		12.5
Isobutane	75-28-5	NA	NA	1000ppm	12.5
n-Hexane	110-54-3	50 ppm	50 ppm		3-7

2. PHYSICAL DATA :

Specific Gravity : 0.7238

Vapor Pressure : ND

% Volatile : 75

Boiling Point : 141 F (initial)

Evaporation Rate : NA

Freezing Point : ND

Vapor Density : > air

Appearance and Odor:

Light amber liquid

pH: NA

Solubility : Negligible in water.

3. FIRE AND EXPLOSION DATA

Flashpoint : <20 F Method : TCC

Flammable Limits : propellant LEL:1.8 UEL:9.5

Extinguishing Media : Foam, dry chemical

Unusual Hazards : Low flashpoint is due to propellant. Aerosol cans may explode if heated above 120 F.

4. REACTIVITY AND STABILITY

Stability : Stable

Hazardous decomposition products

: carbon monoxide, hydrogen chloride

Materials to avoid : Aluminum and/or zinc powder.

5. PROTECTION INFORMATION

Ventilation : Sufficient to maintain vapor concentration below TLV.

Respiratory : Self contained breathing apparatus if above TLV.

Gloves : Solvent resistant

Eye & Face : Safety goggles

Other Protective Equipment: Not normally needed for aerosol usage.

MATERIAL SAFETY DATA SHEET

PRODUCT NAME : BELT DRESSING AEROSOL #-HSUS03065

MANUFACTURED BY : CRC INDUSTRIES, INC. PRODUCTS- 3065

885 LOUIS DRIVE, WARMINSTER, PA. 18974

PHONE (215) 674-4300

(Page 2 of 2)

6. HEALTH HAZARD DATA

Primary Routes of Entry : Inhalation, Skin

Signs and Symptoms of Exposure

1. Acute Overexposure:

Inhalation: headaches, dizziness, anesthesia, unconsciousness
Eyes: causes pain and irritation
Skin: defatting and irritation.

2. Chronic overexposure: Repeated overexposures may cause liver and kidney effects.

Medical Conditions Generally Aggravated by Exposure

: High levels (2000+ ppm) of vapor may cause cardiac arrhythmias.

Chemical Listed as Carcinogen : No
or Potential Carcinogen : No
National Toxicology Program
IARC Monographs
OSHA

Emergency and First Aid Procedures : (If symptoms persist, call a physician)

1. Inhalation : Remove to fresh air. Apply artificial respiration if necessary.

2. Eyes : Flush with large amounts of water for 15 minutes.

3. Skin : Wash area with soap and water.

4. Ingestion : DO NOT induce vomiting. Call a physician.

7. SPILL OR LEAK PROCEDURES

Precautions to be taken : Store in a cool, dry area.
in Handling and Storage

Steps to be taken in case : Remove sources of ignition, ventilate area, absorb
Material is released or spilled with inert material.

Waste Disposal : All used and unused Product should be disposed of in
conformance with local, state and federal regulations.

8. SPECIAL PRECAUTIONS AND USE DIRECTIONS :

Propane and isobutane are aerosol propellants. Pressure = 52 psig.

Aerosols may explode if heated above 120 F.

Vapors are heavier than air and will collect in low areas. Be sure of

adequate ventilation.

9. NFPA HAZARD RATINGS

Health:2 Flammability:4 Reactivity:0

10. SARA Information

This product contains the following chemicals that are subject to release
reporting under Section 313 of SARA Title III.

Chemical Name	CAS-#	Percent
n-Hexane	110-54-3	3-7

PREPARED BY: Adam Selisker ORIGINAL DATE or DATE OF REVISION: 04/12/96